



715 Stadium Dr., Arlington, TX 76011  
817-274-7553 phone \* 817-548-1358 fax  
www.winsystems.com

## Product Change Notice

---

---

Release Date: June 24, 2012  
Product Name: CFLASH-G-4096-I and CFLASH-G-8192-I  
Models Affected: all variations

### Purpose of Notification:

Due to a scheduled die shrink by Samsung in Q4 of 2013 the CFLASH-G-4096-I and CFLASH-G-8192-I will be discontinued. The NAND FLASH controller used in the CFLASH-G-4096-I and CFLASH-G-8192-I is not capable of supporting the new NAND die. WinSystems offers a replacement for both modules that use a newer and faster controller. The replacement modules offer a slightly smaller amount of disk space because they have an advanced wear-leveling scheme that requires more spare blocks.

Customers may need to rebuild their master CompactFlash images to accommodate the change in size.

Contact your WinSystems' Applications Engineer to start the re-qualification process.

### Product Identification:

Part Number	Description	Replacement
CFLASH-G-4096-I	4G industrial CompactFlash	CF-DC-A-4G-I
CFLASH-G-8192-I	8G industrial CompactFlash	CF-DC-A-8G-I

### Key Dates:

Last time buy of existing revision: November 27, 2013

Last time ship of existing revision: NC/NR Blanket orders will be accepted with a last ship date not to exceed September 30, 2014.

An important part of WinSystems' product lifecycle management program is to provide customers with advance notice of changes that might affect long-term product usage or availability. WinSystems will attempt to provide as much advance notice as possible of changes that affect the form, fit or function of the product, except when an immediate change is required.

\*\*\*\*\*

If you have technical questions about this product notification, please contact your WinSystems' Applications Engineer directly, or you can call 817-274-7553.

Jeff Childs  
G.T. Hilliard  
Kerry West  
Dean Sullivan

[jeff@winsystems.com](mailto:jeff@winsystems.com)  
[george@winsystems.com](mailto:george@winsystems.com)  
[kerry@winsystems.com](mailto:kerry@winsystems.com)  
[dsullivan@winsystems.com](mailto:dsullivan@winsystems.com)

PCN 13-0002,  
CFLASH-G-4096-I and CFLASH-G-8192-I